

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
2011-26-07	To prevent engine failure due to migration of the magneto impulse coupling stop pin		N/A		X		Royal Aircraft Services, LLC CRS JZRR651K
2011-10-09	To prevent seat slippage or the seat roller housing from departing from the seat rail				X		Royal Aircraft Services, LLC CRS JZRR651K
2008-26-10	Correction - Prevent erroneous indications from the altimeter, airspeed, and vertical speed indicators				X		Royal Aircraft Services, LLC CRS JZRR651K
2008-10-02	To prevent erroneous indications from the altimeter, airspeed, and vertical speed indicators			X			Royal Aircraft Services, LLC CRS JZRR651K
2008-02-18	To prevent premature separation of the collar		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K
2005-14-11	Prevent blade failure that could result in separation of a propeller blade		N/A Not overhauled by Southern California Propeller Service.	X			Royal Aircraft Services, LLC CRS JZRR651K
2004-19-01	CORRECTION - Prevent slippage of the pilot/co-pilot shoulder harness			X			Royal Aircraft Services, LLC CRS JZRR651K
2002-26-03	Detect and correct incorrect installation of the air filter		N/A by P/N	X			Royal Aircraft Services, LLC CRS JZRR651K
2002-13-04	CORRECTION - Prevent engine failure and loss of control of the airplane		Superseded by AD2011-26-07	X			Royal Aircraft Services, LLC CRS JZRR651K
PL2000-11-51	Possible engine failure		Superseded by AD2002-13-04	X			Royal Aircraft Services, LLC CRS JZRR651K
99-27-02	Inadequate supply of fuel			X			Royal Aircraft Services, LLC CRS JZRR651K
98-17-11	Crankshafts			X			Royal Aircraft Services, LLC CRS JZRR651K
98-01-06	Precision carburetors				X		Royal Aircraft Services, LLC CRS JZRR651K
97-01-13	Fuel, oil, or hydraulic hose			X			Royal Aircraft Services, LLC CRS JZRR651K
96-09-06	Prevent gasket particles from entering the carburetor		BA-5110 Rev. H Filter assembly installed. No further action required.		X		Royal Aircraft Services, LLC CRS JZRR651K
95-21-15	Engine teardown and analytical inspect.			X			Royal Aircraft Services, LLC CRS JZRR651K
95-03-02	Brackett air filter gasket		Superseded by AD96-09-06		X		Royal Aircraft Services, LLC CRS JZRR651K
94-06-09	Teledyne/Bendix magnetos			X			Royal Aircraft Services, LLC CRS JZRR651K
94-05-05 R1	Rocker shaft bosses				X		Royal Aircraft Services, LLC CRS JZRR651K
94-01-03 R2	Teledyne/Bendix magnetos			X			Royal Aircraft Services, LLC CRS JZRR651K
93-19-04	Precision carburetors			X			Royal Aircraft Services, LLC CRS JZRR651K
93-18-03	Precision carburetors		Superseded by AD98-01-06	X			Royal Aircraft Services, LLC CRS JZRR651K
93-11-03	Connecting Rod		N/A by S/N	X			Royal Aircraft Services, LLC CRS JZRR651K

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
93-10-02	Cylinder valve retainer		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K
90-06-03 R1	Heater/muffler		N/A by Aircraft S/N	X			Royal Aircraft Services, LLC CRS JZRR651K
88-02-04	Marvel Schebler carburetors		N/A by Model #	X			Royal Aircraft Services, LLC CRS JZRR651K
87-20-03 R2	Seat tracks		Superseded by AD2011-10-09		X		Royal Aircraft Services, LLC CRS JZRR651K
87-17-06	AM Safe restraint system		N/A by P/N	X			Royal Aircraft Services, LLC CRS JZRR651K
86-26-04	Shoulder harness adjuster		Superseded by AD2004-19-01	X			Royal Aircraft Services, LLC CRS JZRR651K
83-17-06	Aileron balance weights		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K
82-20-01	Bendix magnetos		N/A by S/N	X			Royal Aircraft Services, LLC CRS JZRR651K
82-07-02	Engine crankcase breather		PCW	X			Royal Aircraft Services, LLC CRS JZRR651K
81-15-03	Brackett air filters		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K
79-10-14 R1	Fuel tank venting	6/25/1979	PCW by installation of vented fuel caps in accordance with SE 77-6	X			Royal Aircraft Services, LLC CRS JZRR651K
79-08-03	Electrical system		PCW	X			Royal Aircraft Services, LLC CRS JZRR651K
77-02-09	Wing flap system		N/A by S/N	X			Royal Aircraft Services, LLC CRS JZRR651K
76-07-12	Bendix switches	7-3-2014 Tach: 3688.9	Complied with by operational check. No discrepancies noted at this time.		X	100 hours or Annual	Royal Aircraft Services, LLC CRS JZRR651K
74-26-09	Bendix magnetos		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K
74-06-02	AVCON mufflers		N/A not installed.		X		Royal Aircraft Services, LLC CRS JZRR651K
74-04-01	Aft fuselage bulkhead assy		N/A by S/N	X			Royal Aircraft Services, LLC CRS JZRR651K
73-23-07	Defective spar attach fittings		N/A by S/N	X			Royal Aircraft Services, LLC CRS JZRR651K
73-17-01	Fuel transfer pump placard		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K
73-07-04	Bendix Magnetos		Superseded by AD94-01-03 R2.	X			Royal Aircraft Services, LLC CRS JZRR651K
72-07-02	Selector valve placard		PCW	X			Royal Aircraft Services, LLC CRS JZRR651K
72-06-05 R2	Marvel Schebler carburetors		PCW	X			Royal Aircraft Services, LLC CRS JZRR651K
71-22-02 R1	Cracks in nose gear fork	8/29/1973	PCW by replacement of nose gear fork kits SK182-34C and SK150-38.		X		Royal Aircraft Services, LLC CRS JZRR651K
71-18-01	Fuel selector valve placard		N/A by S/N	X			Royal Aircraft Services, LLC CRS JZRR651K
69-24-03	Marvel Schebler carburetors		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
69-15-03	Muffler assembly		N/A		X		Royal Aircraft Services, LLC CRS JZRR651K
69-09-03 R3	Propeller blade tip failures		N/A by Model #	X			Royal Aircraft Services, LLC CRS JZRR651K
68-17-04	Stall warning system		N/A by S/N	X			Royal Aircraft Services, LLC CRS JZRR651K
66-23-02	Fixed pitch metal propellers		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K
59-10-03	Flasher switch		N/A	X			Royal Aircraft Services, LLC CRS JZRR651K